

# VLT

## IP66 VLT® drives operate flawlessly in Indian dairy

The Indian dairy VRS Limited in Malanpur (Gwalior) use hydrochloric acid, caustic and corrosive cleaning agents in its CIP cleaning of the equipment. IP66 enclosed VLT® drives mounted near the motors showed easy to install and operate.

“Danfoss offered a IP66 solution with overall low cost of installation and extremely good protection as far as dairy industry is concern” says Mr Nityanand Singh, plant manager. He find the VLT® drives safe and easy to maintain. As the drives are mounted in production area, the machine performance can be observed by operator, which is experiences as an important benefit.

### Easy trouble shooting

The VLT® drives offer easy trouble shooting because of less cables and because the operator is able to analyse the process parameters.

The dairy has 82 pcs. IP66 enclosed VLT® drives installed in the range from 1.5 kW to 75 KW . The rest of the drives are IP54.



### Training

On each and every step of commission the customer is trained in trouble shooting and safe operation standards.



Contact:  
**Sandeep Sharma**  
Executive Sales  
Gurgaon , India

Danfoss can accept no responsibility for possible errors in catalogues, brochures and other printed material. Danfoss reserves the right to alter its products without notice. This also applies to products already on order provided that such alterations can be made without substantial change being necessary in special orders already agreed. All trademarks in this material are property of their respective companies. Danfoss and the Danfoss logo typeface trademarks of Danfoss A/S. All rights reserved.