


Ordering

Standard program, 1×Pt100, extension length = 50 mm

Insertion Length (mm)	Electrical Connection	Transmitter Setting	Process Connection	
			G1/2A / 200° C	
			Weight	Code No.
50	4-20mA, 2-wire	±0 to 100° C	0.42	084Z6171
80			0.44	084Z6172
100			0.45	084Z6173
150			0.48	084Z6174
200			0.51	084Z6175

Dimensions



Process connection	Width across flats
G½A	HEX 27